











Accessories

| Order code | Description | |
|------------|---|---|
| VPK01 | Interface splitbox JB1 |  |
| VPK02 | Interface splitbox JB1+ power supply |  |
| PSU01 | 12 Volt power supply, switched mode |  |
| HAC001 | Swagelok® fitting for insertion probe |  |
| HAC002 | Teflon® ferrules (set of 5) |  |
| HAC003 | Safety chain for insertion probe |  |
| HAC004 | Multi pole cable (spare) |  |
| HAC007 | Transport case for insertion probes up to 40 cm |  |